Change Direction of CT Data

For v1.36

Change direction of the CT data and export as new sectional image sequences.

Change to “Surface Rendering”.
Open “Voxel Rotational Trim” dialog from “Main Control”, and blue green target is drawn.





Rotate the object to adjust direction to the target.



Adjust size of the target so that the object does not protrude it.





Check “target follows object’s move” and select “Tool (T)” > “Rotation (R)” to open “Rotation” dialog.





Rotate the object and the target by 90 degrees by buttons on Rotation dialog, ascertain the object does not protrude the target and adjust.



Press “Output Image” button and “OK”.





Select folder and press “OK”.



CT data is displayed by changed direction from reopened new sectional image sequences.